

OSHA Citation Tracking
Other than Serious Violations FY 2003

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
Naval Aviation Depot, Cherry Point, NC	00146	2/27/2003	Complaint	Other	1910.1001(d)(1)	Asbestos exposure determinations. Employee exposure shall be made from breathing zone air samples that are representative of the 8-hour TWA and 30-minute short-term exposures of each employee.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	6/18/2003	\$7,000
NAS Key West, FL	00213	4/16/2003	Planned	Other	1910.1200(g)(8)	HAZCOM. The employer shall maintain in the workplace copies of the required material safety data sheets for each hazardous chemical, and shall ensure that they are readily accessible during each work shift to employees when they are in their work area(s). (Electronic access, microfiche, and other alternatives to maintaining paper copies of the material safety data sheets are permitted as long as no barriers to immediate employee access in each workplace are created by such options.)	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 7 Hazardous Material Control and Management	7/7/2003	\$7,000
Puget Sound Naval Shipyard Bremerton, WA	00251	5/28/2003	Planned	Other	1910.026(c)(2)	Ladders having defects are to be marked and taken out of service until repaired by either maintenance department or the manufacturer.	OPNAVINST 5100.23F Chapter 5 Prevention and Control of Workplace Hazards	6/16/2003	\$7,000
Puget Sound Naval Shipyard Bremerton, WA	00251	5/28/2003	Planned	Other	1910.303(g)(1)	Working space about electric equipment. Sufficient access and working space shall be provided and maintained about all electric equipment to permit ready and safe operation and maintenance of such equipment.	OPNAVINST 5100.23F Chapter 5 Prevention and Control of Workplace Hazards	6/16/2003	\$7,000

Puget Sound Naval Shipyard Bremerton, WA	00251	5/28/2003	Planned	Other	1910.334(a)(2)(i)	Electrical equipment. Portable cord and plug connected equipment and flexible cord sets (extension cords) shall be visually inspected before use on any shift for external defects (such as loose parts, deformed and missing pins, or damage to outer jacket or insulation) and for evidence of possible internal damage (such as pinched or crushed outer jacket). Cord and plug connected equipment and flexible cord sets (extension cords) which remain connected once they are put in place and are not exposed to damage need not be visually inspected until they are relocated.	OPNAVINST 5100.23F Chapter 5 Prevention and Control of Workplace Hazards	6/16/2003	\$7,000
Puget Sound Naval Shipyard Bremerton, WA	00251	5/28/2003	Planned	Other	1910.334(a)(2)(ii)	Electrical equipment. If there is a defect or evidence of damage that might expose an employee to injury, the defective or damaged item shall be removed from service, and no employee may use it until repairs and tests necessary to render the equipment safe have been made.	OPNAVINST 5100.23F Chapter 5 Prevention and Control of Workplace Hazards	6/16/2003	\$7,000

Note:

The abatement date is established by the OSHA area office. The period of time to abate a hazard is the shortest interval that an employer can reasonably be expected to correct the violation.

The OSHA Act authorizes civil penalties be assessed for each alleged violation. Most Federal agencies are exempt from these fines. Penalties are based on four factors: 1) the gravity of the violation: 2) the size of the business; 3) the good faith of the employer; 4) the employer's history of previous violations.